



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Collier

License Number: 2102780

EKOS CADENZA

License Type: Lodging

8368 CADENZA RD , NAPLES 34114

Insp Date: 07/11/2025

Inspection Number: 1624511

Insp Type: Lodging-Licensing Inspection

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2329325

WESTCHESTER APARTMENTS

License Type: Lodging

516 15 ST , MIAMI BEACH 33139

Insp Date: 07/11/2025

Inspection Number: 1642261

Insp Type: Routine - Lodging

Disposition: Warning Issued

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.Observed fire alarm panel at the front entrance with trouble alarm light on.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2316685

MIAMI SUN HOTEL

License Type: Lodging

226 NE 1ST AVENUE , MIAMI 33132

Insp Date: 07/07/2025

Inspection Number: 1184981

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

01-06-4

Portable fire extinguisher locked in a box with no means of access to the fire extinguisher. For reporting purposes only. Near room #202.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Dade

License Number: 2328452

COURTYARD BY MARRIOTT

License Type: Lodging

1530 WASHINGTON AVE , MIAMI BEACH 33139

Insp Date: 07/07/2025

Inspection Number: 1184707

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2329244

EXTENDED STAY AMERICA #1760

License Type: Lodging

298 SW 15 RD , MIAMI 33129

Insp Date: 07/07/2025

Inspection Number: 1185808

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Dade

License Number: 2329325

EUROSTARS LANGFORD

License Type: Lodging

121 SE 1 ST , MIAMI 33131

Insp Date: 07/08/2025

Inspection Number: 1185398

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only. ****Repeat Violation****

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2329442

WYNDHAM GARDEN MIAMI INTERNATIONAL AIRPORT

License Type: Lodging

4909 NW 36 ST , MIAMI SPRINGS 33166

Insp Date: 07/11/2025

Inspection Number: 1185849

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only. ****Repeat Violation****

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Dade

License Number: 2329369

CONGRESS BUILDING

License Type: Lodging

111 NE 2 AVE , MIAMI 33132

Insp Date: 07/07/2025

Inspection Number: 1639376

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2329183

COURTYARD BY MARRIOTT MIAMI DOLPHIN MALL

License Type: Lodging

11275 NW 12 ST , MIAMI 33172

Insp Date: 07/07/2025

Inspection Number: 1185279

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

08-01-4

Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. Observed 099989, 03/25/2025. 136918, 03/25/2025.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Dade

License Number: 2329244

EXTENDED STAY AMERICA #1760

License Type: Lodging

298 SW 15 RD , MIAMI 33129

Insp Date: 07/07/2025

Inspection Number: 1185808

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

08-01-4

Boiler certificate or insurance inspector's boiler report expired. Observed boiler certificate for unit 097115 and 097116 expired 08-12-2022. For reporting purposes only.
Repeat Violation

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2329040

BENTLEY BEACH HOTEL

License Type: Lodging

101 OCEAN DRIVE , MIAMI BEACH 33139

Insp Date: 07/07/2025

Inspection Number: 1186326

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

08-03-4

No boiler certificate or insurance inspector's boiler report available. For reporting purposes only. **Repeat Violation**

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Dade

License Number: 2329494

YOTEL MIAMI

License Type: Lodging

227 NE 2 ST , MIAMI 33132

Insp Date: 07/08/2025

Inspection Number: 1185823

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

08-03-4

Observation

No boiler certificate or insurance inspector's boiler report available. For reporting purposes only.

Violation Citation

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2304760

CONSUELO BETANCOR APARTMENTS

License Type: Lodging

5980 W FLAGLER ST , MIAMI 33144

Insp Date: 07/10/2025

Inspection Number: 1592566

Insp Type: Routine - Lodging

Disposition: Call Back - Admin. complaint recommended

Violation Code

01-06-4

Observation

- From initial inspection : Portable fire extinguisher locked in a box with no means of access to the fire extinguisher. For reporting purposes only. Observed outside unit 5; no hammer. - From follow-up inspection 2025-07-10: **Time Extended**

Violation Citation

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Dade

License Number: 2300391

2110 W FLAGLER ST LLC

License Type: Lodging

2110 W FLAGLER ST , MIAMI 33135

Insp Date: 07/10/2025

Inspection Number: 1594546

Insp Type: Routine - Lodging

Disposition: Call Back - Admin. complaint recommended

Violation Code

Observation

Violation Citation

04-01-4

- From initial inspection : Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only. - From follow-up inspection 2025-07-10: **Admin Complaint**

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2603661

BAYMONT BY WYNDHAM JACKSONVILLE AIRPORT

License Type: Lodging

1153 AIRPORT RD , JACKSONVILLE 32218

Insp Date: 07/10/2025

Inspection Number: 1241641

Insp Type: Complaint Full

Disposition: Warning Issued

Violation Code

Observation

Violation Citation

05-02-5

Hearing-impaired smoke detector is not functioning when tested. For reporting purposes only. In room 203, hearing impaired smoke detector does not activate when test button pushed. **Warning**

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2702303

QUALITY INN

License Type: Lodging

6919 PENSACOLA BLVD , PENSACOLA 32505

Insp Date: 07/10/2025

Inspection Number: 1241643

Insp Type: Complaint Full

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-03-4

Smoke detector/alarm in guest room/unit in disrepair. For reporting purposes only. Smoke detectors in rooms 134 and 202 emitting low battery alarm.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Leon

License Number: 4701621

LOYALTY INN & SUITES

License Type: Lodging

2738 N. MONROE , TALLAHASSEE 32303

Insp Date: 07/11/2025

Inspection Number: 1241597

Insp Type: Complaint Full

Disposition: Warning Issued

Violation Code

Observation

Violation Citation

04-02-4

No smoke detector provided in guest room/unit. For reporting purposes only. Room 122, 322, and a few more room missing smoke alarms.

Reporting: 509.215(1) Each guest room shall be equipped with an approved listed single-station smoke detector meeting the minimum requirements of NFPA-74 Standards for the Installation, Maintenance and Use of Household Fire Warning Equipment. (2) The building has smoke detectors in each guest room individually annunciating to a panel at a supervised location. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 5801498

WYNDHAM AVANTI PALMS RESORT AND CONFERENCE CENTER

License Type: Lodging

6515 INTERNATIONAL DR , ORLANDO 32819

Insp Date: 07/11/2025

Inspection Number: 1186124

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only. By front desk Company called and on the way **Corrective Action Taken**

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Orange

License Number: 5811135

AVANTI RESORT

License Type: Lodging

8738 INTERNATIONAL DR , ORLANDO 32819

Insp Date: 07/08/2025

Inspection Number: 1185839

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

08-01-4

Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only.FL135343, 133038, 130602, 137034, 133040, 135984, 133041 and 133215/all expired 12/14/2024 **Repeat Violation**

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 5801498

WYNDHAM AVANTI PALMS RESORT AND CONFERENCE CENTER

License Type: Lodging

6515 INTERNATIONAL DR , ORLANDO 32819

Insp Date: 07/11/2025

Inspection Number: 1186124

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

Observation

Violation Citation

08-01-4

Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only.FL 131968, FL 096827, FL 135118, FL 099997, FL 121919, FL 121926, expired 12/14/24

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Orange

License Number: 5808761

**FAIRFIELD INN & SUITES BY MARRIOTT ORLANDO LAKE
BUENA VISTA**

License Type: Lodging

12191 S APOPKA VINELAND RD , ORLANDO 32836

Insp Date: 07/10/2025

Inspection Number: 1184767

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No
Further Action

Violation Code

Observation

Violation Citation

08-01-4

Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. Observed boiler certificates expired posted in the boiler room, General Manager notify at time of inspection.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 5809417

EXTENDED STAY AMERICA #1639

License Type: Lodging

6443 WESTWOOD BLVD , ORLANDO 32821

Insp Date: 07/10/2025

Inspection Number: 1186388

Insp Type: Complaint Full

Disposition: Call Back - Complied

Violation Code

Observation

Violation Citation

08-01-4

- From initial inspection : Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. ****Repeat Violation**** - From follow-up inspection 2025-07-10: ****Time Extended****

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Report Date: 07/12/2025

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Palm Beach

License Number: 6012102

UPTOWN 22 LP

License Type: Lodging

2210 N AUSTRALIAN AVE , WEST PALM BEACH 33407

Insp Date: 07/09/2025

Inspection Number: 1644700

Insp Type: Complaint Full

Disposition: Warning Issued

Violation Code

Observation

Violation Citation

01-02-4

Portable fire extinguisher pressure gauge indicates the extinguisher is in need of recharge. For reporting purposes only. First floor near unit 107 building 2200

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Pinellas

License Number: 6209940

HAMPTON AT CLW RETIREMENT CTR

License Type: Lodging

1099 MCMULLEN BOOTH RD , CLEARWATER 33759

Insp Date: 07/10/2025

Inspection Number: 1583397

Insp Type: Routine - Lodging

Disposition: Call Back - Complied

Violation Code

Observation

Violation Citation

08-01-4

- From initial inspection : Boiler certificate or insurance inspector's boiler report expired. Expired 1/10/2025 Boilers were inspected on 1/23/2025 . Deficiencies noted . Establishment working to address these deficiencies For reporting purposes only. - From follow-up inspection 2025-07-10: Per property manager , she is working with Mecon company to address deficiencies. **Time Extended**

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 6204885

BEST WESTERN PLUS YACHT HARBOR INN

License Type: Lodging

150 MARINA PLAZA , DUNEDIN 34698

Insp Date: 07/09/2025

Inspection Number: 1240706

Insp Type: Routine - Lodging

Disposition: Call Back - Admin. complaint recommended

Violation Code

Observation

Violation Citation

05-02-5

- From initial inspection : Hearing-impaired smoke detector is not functioning when tested. For reporting purposes only. Gentex hearing impaired smoke detector not flashing when tested. There is another Genex hearing impaired smoke detector that is working properly. Establishment has 52 rooms. Discussed with operator the need to have 1 per 50 rooms. - From follow-up inspection 2025-07-09: 1 gentex hearing impaired smoke detector observed and tested. It is properly working. There are 54 rooms, operator is required to have 2 hearing impaired smoke detectors. **Admin Complaint**

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Sarasota

License Number: 6803406

License Type: Lodging

LA QUINTA INN AND SUITES SARASOTA DOWNTOWN

1803 N TAMIAMI TRL , SARASOTA 34234

Insp Date: 07/09/2025

Inspection Number: 1186459

Insp Type: Complaint Full

Disposition: Inspection Completed - No Further Action

Violation Code

06-02-4

Observation

Door marked as an exit is blocked. For reporting purposes only.Observed their plaza dumpster left stairway fire exit door blocked off with caution tape.The door functions but operators state they put up the tape to dissuade customers from using it as a normal exit door.

Violation Citation

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 6804033

License Type: Lodging

QUALITY INN

5778 CLARK RD , SARASOTA 34233

Insp Date: 07/11/2025

Inspection Number: 1184598

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No Further Action

Violation Code

04-01-4

Observation

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.Observed trouble code on fire system.

Violation Citation

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Report Date: 07/12/2025

Seminole

License Number: 6904094

NOVEL PARKWAY

License Type: Lodging

1464 LAUREL SOUND LN , SANFORD 32771

Insp Date: 07/11/2025

Inspection Number: 1624225

Insp Type: Complaint Full

Disposition: Call Back - Extension given,
pending

Violation Code

04-01-4

Observation

- From initial inspection : Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.-Site 1 Alarm Panel - From follow-up inspection 2025-06-11: ****Time Extended**** - From follow-up inspection 2025-06-26: -operator states the facility was struck by lightning again and repairs are ongoing ****Time Extended**** - From follow-up inspection 2025-07-11: - operator provided proof of new hardware needing to be replaced, operator stated that the new hardware has been ordered ****Time Extended****

Violation Citation

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 6602527

GERMAN-AMERICAN TRADING &TOURISM

License Type: Lodging

2510 TAMARIND DR , FT PIERCE 34949

Insp Date: 07/10/2025

Inspection Number: 1644721

Insp Type: Complaint Partial

Disposition: Warning Issued

Violation Code

07-02-4

Observation

Frayed electrical wire(s). For reporting purposes only.
Back of building 8

Violation Citation

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Report Date: 07/12/2025

Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

License Number: 7400051

DAYS INN SPEEDWAY

License Type: Lodging

2904 W INTL SPEEDWAY BLVD , DAYTONA BEACH 32124

Insp Date: 07/09/2025

Inspection Number: 1243925

Insp Type: Complaint Full

Disposition: Warning Issued

Violation Code

Observation

Violation Citation

01-06-4

Portable fire extinguisher locked in a box with no means of access to the fire extinguisher. For reporting purposes only. Outside 290, outside 189, 169, 268, 246, 147.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 7400051

DAYS INN SPEEDWAY

License Type: Lodging

2904 W INTL SPEEDWAY BLVD , DAYTONA BEACH 32124

Insp Date: 07/09/2025

Inspection Number: 1243925

Insp Type: Complaint Full

Disposition: Warning Issued

Violation Code

Observation

Violation Citation

08-01-4

Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. Expired 11/10/23 131933

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 7406495

HOLIDAY INN DAYTONA BEACH LPGA

License Type: Lodging

137 AUTOMALL CIR , DAYTONA BEACH 32124

Insp Date: 07/08/2025

Inspection Number: 1184145

Insp Type: Routine - Lodging

Disposition: Warning Issued

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control panel. For reporting purposes only.-trouble and system silence

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Report Date: 07/12/2025

Division of Hotels & Restaurants

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

License Number: 7400051

DAYS INN SPEEDWAY

License Type: Lodging

2904 W INTL SPEEDWAY BLVD , DAYTONA BEACH 32124

Insp Date: 07/11/2025

Inspection Number: 1243925

Insp Type: Complaint Full

Disposition: Call Back - Complied

Violation Code

Observation

Violation Citation

01-06-4	- From initial inspection : Portable fire extinguisher locked in a box with no means of access to the fire extinguisher. For reporting purposes only. Outside 290, outside 189, 169, 268, 246, 147. - From follow-up inspection 2025-07-11: Some boxes with no break devices **Time Extended**	Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.
---------	--	--

License Number: 7400051

DAYS INN SPEEDWAY

License Type: Lodging

2904 W INTL SPEEDWAY BLVD , DAYTONA BEACH 32124

Insp Date: 07/11/2025

Inspection Number: 1243925

Insp Type: Complaint Full

Disposition: Call Back - Complied

Violation Code

Observation

Violation Citation

08-01-4	- From initial inspection : Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. Expired 11/10/23 131933 - From follow-up inspection 2025-07-11: Per manager waiting for inspection **Time Extended**	Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.
---------	--	--