

Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Alachua

License Number: 1100097

TRAVELER'S INN

License Type: Lodging

3103 NW 13 ST , GAINESVILLE 92176

Insp Date: 09/02/2025

Inspection Number: 1241710

Insp Type: Routine - Lodging

Disposition: Inspe

Inspection Completed - No Further Action

Report Date: 09/06/2025

Violation Code

<u>Observation</u>

Violation Citation

04-02-4

No smoke detector provided in guest room/unit. For reporting purposes only.No smoke detector in questroom

225

Reporting: 509.215(1) Each guest room shall be equipped with an approved listed single-station smoke detector meeting the minimum requirements of NFPA-74 Standards for the Installation, Maintenance and Use of Household Fire Warning Equipment. (2) The building has smoke detectors in each guest room individually annunciating to a panel at a supervised location. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 1200071

**MOTEL 6** 

License Type: Lodging

1499 S 6 ST, MACCLENNY 32063

Insp Date: 09/03/2025

Inspection Number: 1243589

Insp Type: Routine - Lodging

Disposition: Inspection Completed - No

Further Action

Violation Code

<u>Observation</u>

**Violation Citation** 

01-02-4

Portable fire extinguisher pressure gauge indicates the extinguisher is in need of recharge. For reporting purposes

only. Fire extinguisher in storage location by unit 110 in

recharge zone.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Report Date: 09/06/2025

### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Bay

License Number: 1305237 **EMERALD BAY APARTMENTS** 

License Type: Lodging 258 S ARNOLD RD HWY 79, PANAMA CITY BEACH 32133

Insp Date: 08/29/2025 Inspection Number: 1644506 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-01-4 Portable fire extinguisher pressure gauge indicates the extinguisher is overcharged. For reporting purposes only.

On front of unit 104.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 1605018 925 OCEAN RESORT

License Type: Lodging 925 SE 20 AVE , DEERFIELD BEACH 33441

Insp Date: 08/29/2025 Inspection Number: 1243216 Insp Type: Routine - Lodging Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble light illuminated on the fire alarm control panel, in

front office. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter

633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 1612878 HOTOLOS HOLLYWOOD

License Type: Lodging 2520 STIRLING RD , HOLLYWOOD 33020

Insp Date: 08/29/2025 Inspection Number: 1243007 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-03-4 Portable fire extinguisher missing from it's designated

location (sign present indicating designated location). For

reporting purposes only. Observed at 411

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food

establishments, and the identification of such violation does not require any firesafety



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Broward** 

License Number: 1620867 **CAMBRIA SUITES FT LAUDERDALE** 

License Type: Lodging 141 SW 19 CT , DANIA 33004

Insp Type: Routine - Lodging Insp Date: 08/29/2025 Inspection Number: 1185583 Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

Violation Citation Violation Code Observation

08-03-4 No boiler certificate or insurance inspector's boiler report

available. For reporting purposes only.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 1619186 **EXTENDED STAY AMERICA SUITES #9638** 

License Type: Lodging 3873 W COMMERCIAL BLVD, TAMARAC 33309

Insp Date: 09/02/2025 Inspection Number: 1244104 Insp Type: Complaint Full Disposition: Call Back - Extension given,

pending

Violation Code Observation **Violation Citation** 

04-01-4 - From initial inspection : Trouble/alarm light illuminated

on the fire alarm control panel. For reporting purposes only. \*\*Repeat Violation\*\* - From follow-up inspection

2025-09-02: \*\*Time Extended\*\*

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



**Fire Observations Reporting** 

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Charlotte

License Number: 1801529 **HOLIDAY INN EXPRESS AND SUITES PUNTA GORDA** 

License Type: Lodging 9075 MAC DR , PUNTA GORDA 33950

Insp Date: 09/04/2025 Inspection Number: 1185709 Disposition: Inspection Completed - No Insp Type: Routine - Lodging

Further Action

Report Date: 09/06/2025

**Violation Citation** Violation Code Observation

08-01-4 Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. Expiration Date:

01/19/2023, \*\*Repeat Violation\*\*

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 2001045 **HUNTERS RUN** 

License Type: Lodging 1535 BLANDING BLVD, MIDDLEBURG 32068

Insp Date: 09/03/2025 Inspection Number: 1645230 Insp Type: Complaint Full Disposition: Inspection Completed - No

Further Action

Violation Code Observation **Violation Citation** 

01-02-4 Portable fire extinguisher pressure gauge indicates the

extinguisher is in need of recharge. For reporting purposes only. Fire extinguishers near units 101,1307,1202,1102,907

and 808 are in the recharge zone. \*\*Repeat Violation\*\*

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety



Report Date: 09/06/2025

### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Clay

License Number: 2001045 HUNTERS RUN

License Type: Lodging 1535 BLANDING BLVD, MIDDLEBURG 32068

Insp Date: 09/03/2025 Inspection Number: 1645230 Insp Type: Complaint Full Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-03-4 Portable fire extinguisher missing from it's designated

location (sign present indicating designated location). For reporting purposes only. Fire extinguishers are missing from boxes near units 401,601,508,1108 and 707. \*\*Repeat

Violation\*\*

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 2000962 HAMPTON INN & SUITES

License Type: Lodging 1735 JEREMIAH ST, MIDDLEBURG 32068

Insp Date: 09/03/2025 Inspection Number: 1185257 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only. Trouble light showing on fire panel. Manager states a part is needed and due to be replaced/repaired today. \*\*Corrective Action Taken\*\*

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2329214 GRAYSON MIAMI

License Type: Lodging 1100 BISCAYNE BLVD , MIAMI 33132

Insp Date: 09/05/2025 Inspection Number: 1185213 Insp Type: Routine - Lodging Disposition: Warning Issued

Violation Code Observation Violation Citation

05-02-5 Hearing-impaired smoke detector is not functioning when

tested. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



Report Date: 09/06/2025

#### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Dade** 

License Number: 2302407 UHLENHAUT INC

License Type: Lodging 265 E 7 ST , HIALEAH 33010

Insp Date: 09/05/2025 Inspection Number: 1645079 Insp Type: Lodging-Licensing Inspection Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only. Observed trouble alarm

illuminated on the fire alarm control panel.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 2331238 2000 BISCAYNE

License Type: Lodging 251 NE 20 ST , MIAMI 33137

Insp Date: 09/04/2025 Inspection Number: 1644682 Insp Type: Lodging-Licensing Inspection Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-03-4 No boiler certificate or insurance inspector's boiler report Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually

available. For reporting purposes only.

for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public localing octablishments or public food octablishments, and the identification of such

lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Dade** 

License Number: 2329498 TRU BY HILTON MIAMI WEST BRICKELL

License Type: Lodging 1931 SW 3 AVE , MIAMI 33129

Insp Date: 09/05/2025 Inspection Number: 1184618 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-01-4 Portable fire extinguisher pressure gauge indicates the

extinguisher is overcharged. For reporting purposes only.

Observed at third floor next to unit 318.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 2329335 FLAGLER STATION RESIDENCE INN

License Type: Lodging 11500 NW 105 ST , MIAMI 33178

Insp Date: 08/29/2025 Inspection Number: 1186107 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-02-4 Portable fire extinguisher pressure gauge indicates the

extinguisher is in need of recharge. For reporting purposes only. Observed fire extinguisher next to room 404 in the

recharge zone.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety



### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Dade** 

License Number: 2329211 MIAMI MANSION MOTEL

License Type: Lodging 611 E OKEECHOBEE RD, HIALEAH 33010

Insp Date: 08/29/2025 Inspection Number: 1184900 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-06-4 Portable fire extinguisher locked in a box with no means of

access to the fire extinguisher. For reporting purposes only. Observed two fire extinguishers locked in a box with no means of access to the fire extinguisher at parking.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 2314364 AIJDE WANOUNOU III

License Type: Lodging 1330 NW 2 ST , MIAMI 33130

Insp Date: 09/04/2025 Inspection Number: 1632178 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-06-4 Portable fire extinguisher locked in a box with no means of

access to the fire extinguisher. For reporting purposes only. Observed both fire extinguishers with no means to access the fire extinguishers near to unit 5 and next to

mailboxes.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety



**Fire Observations Reporting** 

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Dade** 

License Number: 2329211 MIAMI MANSION MOTEL

License Type: Lodging 611 E OKEECHOBEE RD, HIALEAH 33010

Insp Date: 08/29/2025 Inspection Number: 1184900 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only. Observed at main

office. \*\*Repeat Violation\*\*

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 2329207 SPRINGHILL SUITES MIAMI ARTS/HEALTH DISTRICT

License Type: Lodging 1311 NW 10TH AVE , MIAMI 33136

Insp Date: 09/02/2025 Inspection Number: 1187011 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

**Further Action** 

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control Reporting: The division, or its agent, shall notify the local firesafety authority or the

panel. For reporting purposes only.

State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



**Fire Observations Reporting** 

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Dade** 

License Number: 2329242 COURTYARD BY MARRIOTT SOUTH HOMESTEAD

License Type: Lodging 2905 NE 9 ST, HOMESTEAD 33033

Insp Date: 08/29/2025 Inspection Number: 1185527 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. Observed

130160,130161. 12/13/2024.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 2329326 HOLIDAY INN EXPRESS AND SUITES MIAMI AIRPORT EAST

License Type: Lodging 2601 NW 42 AVE , MIAMI 33142

Insp Date: 09/04/2025 Inspection Number: 1185668 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report

expired. For reporting purposes only. Observed boiler certificate 137058 and 137057 both expired on 01-09-

2025. \*\*Repeat Violation\*\*

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Violation Citation** 

**Dade** 

License Number: 2300489 **GENESIS PROPERTY INVESTMENTS** 

License Type: Lodging 1442 SW 3 ST , MIAMI 33135

Insp Date: 08/29/2025 Inspection Number: 1644846 Insp Type: Complaint Full Disposition: Call Back - Extension given,

pending

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u>

01-02-4 - From initial inspection : Portable fire extinguisher pressure gauge indicates the extinguisher is in need of

recharge. For reporting purposes only.By unit 5. - From follow-up inspection 2025-08-29: Portable fire extinguisher pressure gauge indicates the extinguisher is in need of recharge. For reporting purposes only.By unit 5. \*\*Time

Extended\*\*

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 2300489 GENESIS PROPERTY INVESTMENTS

License Type: Lodging 1442 SW 3 ST , MIAMI 33135

Insp Date: 09/05/2025 Inspection Number: 1644846 Insp Type: Complaint Full Disposition: Call Back - Complied

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-02-4 - From initial inspection : Portable fire extinguisher

pressure gauge indicates the extinguisher is in need of recharge. For reporting purposes only.By unit 5. - From follow-up inspection 2025-08-29: Portable fire extinguisher pressure gauge indicates the extinguisher is in need of recharge. For reporting purposes only.By unit 5. \*\*Time Extended\*\* - From follow-up inspection 2025-09-05: Portable fire extinguisher pressure gauge indicates the extinguisher is in need of recharge. For reporting purposes

only.By unit 5 \*\*Time Extended\*\*

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Dade** 

License Number: 2329378 ALTAIR HOTEL

License Type: Lodging 9540 W BAY HARBOR DR, BAY HARBOR ISLANDS 33154

Insp Date: 09/04/2025 Inspection Number: 1186298 Insp Type: Routine - Lodging Disposition: Call Back - Complied

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 - From initial inspection: Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only. Observed balcony certificates expired for FL 134356, 134355 as of 08/26/2022. - From follow-up inspection

2025-09-04: Observed balcony certificates expired for FL 134356, 134355 as of 08/26/2022. \*\*Time Extended\*\*

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 2329541 **RED ROAD RENTALS** 

License Type: Lodging 282 NW 57 AVE , MIAMI 33126

Insp Date: 08/29/2025 Inspection Number: 1598397 Insp Type: Routine - Lodging Disposition: Call Back - Admin. complaint

recommended

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 - From initial inspection : Trouble/alarm light illuminated

on the fire alarm control panel. For reporting purposes only, - From follow-up inspection 2025-08-29: \*\*Time

Extended\*\*

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Duval** 

License Number: 2613245 SHERATON JACKSONVILLE HOTEL

License Type: Lodging 10605 DEERWOOD PARK BLVD , JACKSONVILLE 32256

Insp Date: 09/04/2025 Inspection Number: 1185518 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report

expired. For reporting purposes only. One boiler certificate expired 8.25.25. Also, one boiler certificate missing from

boiler room.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 3200101 LAKEPORT HUNTING & FISHING LODGE

License Type: Lodging 1077 LAKEPORT PLAZA , LAKEPORT 33471

Insp Date: 09/05/2025 Inspection Number: 1243004 Insp Type: Routine - Lodging Disposition: Call Back - Complied

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-02-4 - From initial inspection : Portable fire extinguisher pressure gauge indicates the extinguisher is in need of

recharge. For reporting purposes only: between units 107 and 106, also at unit 126 \*\*Repeat Violation\*\* - From follow-up inspection 2025-09-05: Operator has contacted

them to recharge but it has not been recharged. \*\*Time

Extended\*\* \*\*Corrective Action Taken\*\*

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

PDF Generated from Qlik App: HR518-DET\_Fire Observations



Report Date: 09/06/2025

### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Hillsborough

License Number: 3905670 EMBASSY SUITES BY HILTON TAMPA AIRPORT WESTSHORE

License Type: Lodging 555 N WESTSHORE BLVD, TAMPA 33609

Insp Date: 09/03/2025 Inspection Number: 1184792 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report

expired. For reporting purposes only.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 4100202 OCEAN BREEZE INN VERO BEACH
License Type: Lodging 3384 OCEAN DR, VERO BEACH 32963

Insp Date: 09/05/2025 Inspection Number: 1243277 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-07-4 Trouble/alarm light illuminated on the smoke detector

panel connected to the fire alarm system. For reporting purposes only. System trouble alerted-battery charger

trouble

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



Report Date: 09/06/2025

### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Marion** 

License Number: 5202478 SPRINGHILL SUITES OCALA

License Type: Lodging 4100 SW 40 ST , OCALA 34474

Insp Date: 09/03/2025 Inspection Number: 1184714 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

**Further Action** 

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-02-4 Portable fire extinguisher pressure gauge indicates the extinguisher is in need of recharge. For reporting purposes

only.On 7th floor near room 702.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety



**Fire Observations Reporting** 

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Martin** 

License Number: 5300993 PIRATE'S COVE RESORT & MARINA

License Type: Lodging 4307 SE BAYVIEW ST, STUART 34997

Insp Date: 08/29/2025 Inspection Number: 1185722 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 5300742 HUTCHINSON ISLAND MARRIOTT BEACH RESORT & MARINA

License Type: Lodging 555 NE OCEAN BLVD, STUART 34996

Insp Date: 08/29/2025 Inspection Number: 1186352 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

**Further Action** 

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report

expired. For reporting purposes only.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Report Date: 09/06/2025

#### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Monroe** 

License Number: 5403195 MARRIOTT COURTYARD

License Type: Lodging 2146 OVERSEAS HWY, MARATHON 33050

Insp Date: 09/02/2025 Inspection Number: 1185166 Insp Type: Routine - Lodging Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter

State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 5403212 BLUE WATER RESORT HOSPITALITY LLC

License Type: Lodging 2222 OVERSEAS HWY, MARATHON 33050

Insp Date: 09/02/2025 Inspection Number: 1183940 Insp Type: Routine - Lodging Disposition: Warning Issued

Violation Code Observation Violation Citation

04-01-4 Trouble/alarm light illuminated on the fire alarm control Reporting: The division, or its agent, shall notify the local firesafety authority or the

panel. For reporting purposes only.

State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 5403195 MARRIOTT COURTYARD

License Type: Lodging 2146 OVERSEAS HWY, MARATHON 33050

Insp Date: 09/02/2025 Inspection Number: 1185166 Insp Type: Routine - Lodging Disposition: Warning Issued

Violation Code Observation Violation Citation

08-01-4 Boiler certificate or insurance inspector's boiler report

audical Farmanation armana and

expired. For reporting purposes only.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Monroe** 

License Number: 5403212 BLUE WATER RESORT HOSPITALITY LLC

License Type: Lodging 2222 OVERSEAS HWY, MARATHON 33050

Insp Date: 09/02/2025 Inspection Number: 1183940 Insp Type: Routine - Lodging Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low

for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 5400075 ANGLER (BLDG 1), ATLANTIC SUNRISE (BLDG 2), MIRAMAR

(BLDG 3)

License Type: Lodging 84001 OVERSEAS HWY , ISLAMORADA 33036

Insp Date: 09/05/2025 Inspection Number: 1242374 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

**Further Action** 

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and

the identification of such violation does not require any firesafety inspection



Report Date: 09/06/2025

#### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Monroe** 

License Number: 5400007 THREE WATERS RESORT MARINA - SCARLET CORAL

**COTTAGES** 

License Type: Lodging 84001 OVERSEAS HWY , ISLAMORADA 33036

Insp Date: 09/05/2025 Inspection Number: 1242325 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 5400679 THREE WATERS RESORT MARINA - ISLA (B4), WINDLEY

(B5)

License Type: Lodging 84001 OVERSEAS HWY , ISLAMORADA 33036

Insp Date: 09/05/2025 Inspection Number: 1243376 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



Fire Observations Reporting

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Orange** 

License Number: 5809240 HOLIDAY INN RESORT ORLANDO SUITES - WATERPARK

License Type: Lodging 14500 CONTINENTAL GATEWAY, ORLANDO 32821

Insp Date: 09/02/2025 Inspection Number: 1187234 Insp Type: Complaint Full Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report

expired. For reporting purposes only. \*\*Repeat Violation\*\* for po

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 5810516 COUNTRY INN & SUITES ORLANDO AIRPORT

License Type: Lodging 5440 FORBES PL , ORLANDO 32812

Insp Date: 09/05/2025 Inspection Number: 1184603 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

**Further Action** 

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report

expired. For reporting purposes only.(#133807

#133808#131555 expired 4-10-2025)

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Orange** 

License Number: 5809240 HOLIDAY INN RESORT ORLANDO SUITES - WATERPARK

License Type: Lodging 14500 CONTINENTAL GATEWAY, ORLANDO 32821

Insp Date: 09/02/2025 Inspection Number: 1183872 Insp Type: Complaint Full Disposition: Call Back - Extension given,

pending

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 - From initial inspection: Boiler certificate or insurance inspector's boiler report expired. For reporting purposes

only. \*\*Repeat Violation\*\* - From follow-up inspection

2025-09-02: \*\*Time Extended\*\*

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 5900233 MAINGATE LAKESIDE RESORT

License Type: Lodging 7769 W. IRLO BRONSON MEMORIAL HWY. , KISSIMMEE 34747

Insp Date: 09/02/2025 Inspection Number: 1187351 Insp Type: Complaint Full Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually

expired. For reporting purposes only. \*\*Repeat Violation\*\*

for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Palm Beach** 

License Number: 6013279 COURTYARD BY MARRIOTT WEST PALM BEACH AIRPORT

License Type: Lodging 1800 CENTRE DR. E. , WEST PALM BEACH 33401

Insp Date: 08/29/2025 Inspection Number: 1184719 Insp Type: Routine - Lodging Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low

for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting

purposes only.

License Number: 6005626 ROYAL PALM MOTEL

License Type: Lodging 5445 LAKE WORTH RD, GREENACRES 33463

Insp Date: 08/29/2025 Inspection Number: 1243477 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-02-4 Portable fire extinguisher pressure gauge indicates the Reporting: (d) The

extinguisher is in need of recharge. For reporting purposes only.Portable Fire extinguisher next to room 102 in recharge zone, discussed with operator, \*\*Repeat

Violation\*\*

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



Report Date: 09/06/2025

### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Palm Beach

License Number: 6001961 **ECONOMY INN OF LAKE WORTH** 

License Type: Lodging 1104 S DIXIE HWY , LAKE WORTH 05232

Insp Date: 08/29/2025 Inspection Number: 1242745 Inspection Completed - No Insp Type: Routine - Lodging Disposition:

Further Action

Violation Code Observation Violation Citation

04-02-4 No smoke detector provided in guest room/unit. For reporting purposes only.Room 214, no smoke detector in

room.

Reporting: 509.215(1) Each quest room shall be equipped with an approved listed single-station smoke detector meeting the minimum requirements of NFPA-74 Standards for the Installation, Maintenance and Use of Household Fire Warning Equipment. (2) The building has smoke detectors in each quest room individually annunciating to a panel at a supervised location. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 6005777 **LAGO MOTOR INN** 

License Type: Lodging 714 S DIXIE HWY, LAKE WORTH 33460

Insp Date: 08/29/2025 Inspection Number: 1241712 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Violation Code Observation **Violation Citation** 

Trouble/alarm light illuminated on the smoke detector 04-07-4

panel connected to the fire alarm system. For reporting

purposes only. The portable hearing impaired smoke

detector light does not illuminate.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



**Fire Observations Reporting** 

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

**Pinellas** 

License Number: 6201769

**SAFETY HARBOR RESORT** 

License Type: Lodging

105 N BAYSHORE DR , SAFETY HARBOR 34695

Insp Date: 09/04/2025

Inspection Number: 1187257

Insp Type: Complaint Full

Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

Violation Code

Observation

Violation Citation

08-01-4

Boiler certificate or insurance inspector's boiler report expired. For reporting purposes only.Boilers were inspected by the fire marshal on 10/7/24. Establishment had attempted to to get certificate from the state and are being

told that they are behind in issuing certificates.

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.

License Number: 6215767

**HILTON HOTEL ST. PETERSBURG CARILLON PARK** 

License Type: Lodging 950 LAKE CARILLON DR, ST. PETERSBURG 33716

Insp Date: 09/02/2025

Inspection Number: 1187159

Insp Type: Lodging-Licensing Inspection

Disposition:

Inspection Completed - No

Further Action

Violation Code

Observation

Violation Citation

08-04-4

Boiler certificate not posted in the boiler room. For

reporting purposes only.

Reporting: 61C-1.004(10) The insurance inspector's boiler report shall be posted in the boiler room. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



**Fire Observations Reporting** 

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Sarasota

License Number: 6804763 ART OVATION HOTEL

License Type: Lodging 1255 N PALM AVE, SARASOTA 34236

Insp Date: 09/03/2025 Inspection Number: 1183961 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 6903392 COURTYARD LAKE MARY

License Type: Lodging 135 INTERNATIONAL PKWY , LAKE MARY 32746

Insp Date: 09/05/2025 Inspection Number: 1185573 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Violation Code Observation Violation Citation

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 7406039 HUNTERS CREEK APRTMENTS

License Type: Lodging 930 HUNTERS CREEK DR , DELAND 32720

Insp Date: 09/02/2025 Inspection Number: 1645168 Insp Type: Complaint Full Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control Rep

panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



Report Date: 09/06/2025

### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

License Number: 7405788 EXTENDED STAY AMERICA #1564

License Type: Lodging 255 BILL FRANCE BLVD , DAYTONA BEACH 32114

Insp Date: 08/29/2025 Inspection Number: 1187256 Insp Type: Complaint Partial Disposition: Warning Issued

Violation Code Observation Violation Citation

07-01-4 Exit light broken by guest laundry. For reporting purposes only. \*\*Corrected On-Site\*\*

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under

the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 7405788 EXTENDED STAY AMERICA #1564

License Type: Lodging 255 BILL FRANCE BLVD , DAYTONA BEACH 32114

Insp Date: 08/29/2025 Inspection Number: 1187256 Insp Type: Complaint Partial Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

11-03-4 Gas water heater disrepair. For reporting purposes only.-

per manager 1 water heater is completely not working and

the other is waiting on parts

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under

chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 7406515 STUDIO ONE

License Type: Lodging 1700 S ATLANTIC AVE , DAYTONA BEACH 32118

Insp Date: 09/03/2025 Inspection Number: 1242085 Insp Type: Routine - Lodging Disposition: Warning Issued

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-06-4 Portable fire extinguisher locked in a box with no means of

access to the fire extinguisher. For reporting purposes only.-breaking device missing on box behind unit 21 on

backside

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

License Number: 7401092 QUALITY INN

License Type: Lodging 700 N ATLANTIC AVE , DAYTONA BEACH 32118

Insp Date: 08/29/2025 Inspection Number: 1242518 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

01-06-4 Portable fire extinguisher locked in a box with no means of access to the fire extinguisher. For reporting purposes

only.-break rite box , no breaking device, next to 328

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 7406516 COMFORT SUITES SPEEDWAY

License Type: Lodging 2900 W. INTERNATIONAL SPEEDWAY BLVD , DAYTONA BEACH 32124

Insp Date: 09/04/2025 Inspection Number: 1184169 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

**Further Action** 

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

04-01-4 Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only.-Supervisory and

silenced light on

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



**Fire Observations Reporting** 

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

License Number: 7401092

**QUALITY INN** 

License Type: Lodging

700 N ATLANTIC AVE , DAYTONA BEACH 32118

Insp Date: 08/29/2025

Inspection Number: 1242518

Inspection Number: 1241935

Insp Type: Routine - Lodging

Disposition:

Inspection Completed - No

Further Action

Report Date: 09/06/2025

Violation Code

Observation

Violation Citation

04-01-4

Trouble/alarm light illuminated on the fire alarm control

panel. For reporting purposes only.

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection

certification. For reporting purposes only.

License Number: 7401419

**RANCH MOTEL** 

License Type: Lodging

1028 RIDGEWOOD AVE , HOLLY HILL 32117

Insp Date: 08/29/2025

Insp Type: Routine - Lodging

Inspection Completed - No Disposition:

Further Action

Violation Code

Observation

Violation Citation

04-02-4

No smoke detector provided in guest room/unit. For

reporting purposes only,-room 6.

Reporting: 509.215(1) Each guest room shall be equipped with an approved listed single-station smoke detector meeting the minimum requirements of NFPA-74 Standards for the Installation, Maintenance and Use of Household Fire Warning Equipment. (2) The building has smoke detectors in each guest room individually annunciating to a panel at a supervised location. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

License Number: 7405753 **ECONOLODGE** 

License Type: Lodging 1614 N US 1, ORMOND BEACH 32174

Insp Date: 09/05/2025 Inspection Number: 1241798 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

Report Date: 09/06/2025

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

07-04-4 Electrical outlet detached from wall. For reporting purposes

only.-room 147.

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 7406514 DAYTONA AUTOGRAPH COLLECTION

License Type: Lodging 1870 VICTORY CIR , DAYTONA BEACH 32114

Insp Date: 08/29/2025 Inspection Number: 1185355 Insp Type: Routine - Lodging Disposition: Inspection Completed - No

Further Action

<u>Violation Code</u> <u>Observation</u> <u>Violation Citation</u>

08-01-4 Boiler certificate or insurance inspector's boiler report

expired. For reporting purposes only.-per operator changed

insurance company's and waiting for inspection

Reporting: 61C-1.004(10) The insurance inspector's boiler report is required annually for power boilers and high pressure/high temperature boilers and biannually for low pressure steam or vapor heating boilers. 509.032(2)(d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection certification. For reporting purposes only.



# **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

License Number: 7406516 **COMFORT SUITES SPEEDWAY** 

License Type: Lodging 2900 W. INTERNATIONAL SPEEDWAY BLVD , DAYTONA BEACH 32124

Insp Date: 09/04/2025 Inspection Number: 1184169 Insp Type: Routine - Lodging Inspection Completed - No Disposition:

Further Action

Report Date: 09/06/2025

Violation Citation Violation Code Observation

08-07-4 Gas water not properly vented. For reporting purposes

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or only.-screen on middle water states Blocked Exhaust the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety

inspection certification. For reporting purposes only.

License Number: 7402312 **NOVA 1400** 

1400 S NOVA RD, DAYTONA BEACH 32114 License Type: Lodging

Insp Date: 09/04/2025 Call Back - Complied Inspection Number: 1645102 Insp Type: Complaint Full Disposition:

Violation Code Observation Violation Citation

06-02-4 - From initial inspection : Door marked as an exit is

blocked and locked rear door in maintenance garage . For reporting purposes only. - From follow-up inspection 2025-08-27: \*\*Time Extended\*\* - From follow-up inspection 2025-09-04: Gate in front of door unlocked, 2

slide locks on door

Reporting: The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety inspection



Report Date: 09/06/2025

### **Fire Observations Reporting**

FIRE CODE VIOLATIONS OBSERVED IN PUBLIC FOOD SERVICE & LODGING ESTABLISHMENTS

Volusia

11-03-4

License Number: 7405788 **EXTENDED STAY AMERICA #1564** 

License Type: Lodging 255 BILL FRANCE BLVD , DAYTONA BEACH 32114

Insp Date: 09/02/2025 Inspection Number: 1187256 Insp Type: Complaint Partial Disposition: Call Back - Complied

<u>Violation Code</u> <u>Observation</u>

- From initial inspection: Gas water heater disrepair. For reporting purposes only.-per manager 1 water heater is completely not working and the other is waiting on parts - From follow-up inspection 2025-09-02: Per manager

repaired one water heater. The other needs to be replaced. Per manager there is hot water to building

\*\*Time Extended\*\*

Violation Citation

Reporting: (d) The division, or its agent, shall notify the local firesafety authority or the State Fire Marshal of any readily observable violation of a rule adopted under chapter 633 which relates to public lodging establishments or public food establishments, and the identification of such violation does not require any firesafety